

# HANSER

## Table of Contents

Chris Rauwendaal

Understanding Extrusion

ISBN: 978-3-446-41686-4

For further information and order see

<http://www.hanser.de/978-3-446-41686-4>  
or contact your bookseller.

# Contents

1	Extrusion Machinery . . . . .	1
1.1	What is an Extruder? . . . . .	1
1.2	Different Types of Extruders . . . . .	2
1.2.1	Single Screw Extruders . . . . .	2
1.2.2	Twin Screw Extruders . . . . .	2
1.2.2.1	Co-Rotating Twin Screw Extruders . . . . .	3
1.2.2.2	Counter-Rotating Twin Screw Extruders . . . . .	3
1.2.3	Ram Extruders . . . . .	4
1.3	Components of an Extruder . . . . .	5
1.3.1	The Extruder Screw . . . . .	5
1.3.2	The Extruder Barrel . . . . .	6
1.3.3	The Feed Throat . . . . .	6
1.3.4	The Feed Hopper . . . . .	7
1.3.5	Barrel Heating and Cooling . . . . .	8
1.3.6	Screw Heating and Cooling . . . . .	9
1.3.7	The Breaker Plate . . . . .	9
1.3.8	The Screen Pack . . . . .	10
1.3.8.1	Screen Changers . . . . .	11
1.3.9	The Extrusion Die . . . . .	13
1.3.9.1	Coextrusion Dies . . . . .	14
1.3.10	The Extruder Drive . . . . .	15
1.3.10.1	Coupling between Motor and Gearbox . . . . .	15
1.3.11	The Speed Reducer . . . . .	46
1.3.11.1	Thrust Bearing Assembly . . . . .	17
1.3.12	The Gear Pump . . . . .	18
2	Instrumentation and Control . . . . .	19
2.1	Instrumentation . . . . .	19
2.2	Most Important Process Parameters . . . . .	19
2.2.1	Melt Pressure . . . . .	20
2.2.2	Pressure Transducers . . . . .	21
2.2.3	Temperature Measurement . . . . .	22
2.2.4	Melt Temperature Measurement . . . . .	23
2.2.5	Barrel Temperature Measurement . . . . .	24
2.3	Temperature Control . . . . .	26
2.3.1	On-Off Control . . . . .	26
2.3.2	Proportional Control . . . . .	26
2.3.3	Fuzzy Logic Control . . . . .	29

3	Complete Extrusion Lines . . . . .	31
3.1	Tubing and Pipe Extrusion Lines. . . . .	31
3.2	Film and Sheet Lines Using the Roll Stack Process. . . . .	32
3.3	Film Lines Using Chill Roll Casting . . . . .	33
3.4	Combination of Materials . . . . .	34
3.4.1	Coextrusion . . . . .	35
3.4.2	Extrusion Coating. . . . .	36
3.4.3	Extrusion Lamination . . . . .	36
3.5	Blown Film Lines . . . . .	37
3.6	Extrusion Compounding Lines. . . . .	37
3.7	Profile Extrusion Lines. . . . .	39
4	Plastics and Their Properties Important in Extrusion . . . . .	41
4.1	Thermoplastics and Thermosets . . . . .	41
4.2	Amorphous and Semi-Crystalline Plastics . . . . .	42
4.3	Liquid Crystalline Plastics (LCPs) . . . . .	44
4.4	Elastomers . . . . .	44
4.5	Flow Behavior of Plastic Melts . . . . .	45
4.6	Melt Index . . . . .	46
4.7	The Effect of Shearing . . . . .	47
4.8	Shear Thinning or Pseudoplastic Behavior. . . . .	47
4.9	Effect of Temperature on Viscosity . . . . .	48
4.10	Viscous Heat Generation . . . . .	49
4.11	Thermal Properties . . . . .	49
4.11.1	Thermal Conductivity . . . . .	50
4.11.2	Specific Heat and Enthalpy . . . . .	51
4.11.3	Thermal Stability and Induction Time . . . . .	52
4.11.4	Density . . . . .	53
4.11.5	Melting Point. . . . .	54
4.11.6	Glass Transition Temperature . . . . .	55
5	How an Extruder Works . . . . .	57
5.1	Solids Conveying . . . . .	58
5.1.1	Gravity Induced Conveying . . . . .	58
5.1.2	Drag Induced Conveying . . . . .	61
5.1.3	Starve Feeding . . . . .	62
5.1.4	Grooved Feed Extruders . . . . .	62
5.2	Melting . . . . .	65
5.2.1	Contiguous Solids Melting. . . . .	65
5.2.2	Dispersed Solids Melting. . . . .	66
5.3	Melt Conveying . . . . .	70
5.3.1	Melt Temperatures . . . . .	70
5.4	Mixing . . . . .	73
5.4.1	Distributive Mixing. . . . .	73

5.4.2	Mixing Sections . . . . .	78
5.4.2.1	Distributive Mixing Sections . . . . .	78
5.4.2.2	Dispersive Mixing Sections . . . . .	83
5.5	Degassing . . . . .	89
5.6	Die Forming . . . . .	92
5.6.1	Size and Shape Changes . . . . .	92
5.6.2	Tubing and Pipe Dies . . . . .	96
5.6.3	Flat Film and Sheet Dies . . . . .	98
5.6.4	Profile Dies . . . . .	101
6	How to Run an Extruder . . . . .	103
6.1	Introduction . . . . .	103
6.2	Before Start-up . . . . .	103
6.3	Getting Ready for a Run . . . . .	104
6.4	Starting the Extruder . . . . .	106
6.5	Actual Operation . . . . .	108
6.6	Shut-down . . . . .	109
6.6.1	Purging . . . . .	110
6.7	Safety Issues . . . . .	111
6.7.1	Heat . . . . .	111
6.7.2	Moving Parts . . . . .	111
6.7.3	Electrical . . . . .	112
6.7.4	Weights . . . . .	112
6.7.5	Pressure . . . . .	112
6.8	Inspection and Training . . . . .	113
7	How to Troubleshoot Extrusion Problems . . . . .	117
7.1	Objectives . . . . .	117
7.2	Prerequisites . . . . .	117
7.2.1	Good Instrumentation . . . . .	117
7.2.2	Good Understanding of the Process . . . . .	118
7.2.3	Collect and Analyze Historical Data . . . . .	118
7.2.4	Teamwork . . . . .	118
7.3	Main Types of Problems . . . . .	119
7.3.1	Output Problems . . . . .	119
7.3.1.1	Low Extruder Output . . . . .	119
7.3.1.2	Variation in Extruder Output . . . . .	121
7.3.2	Appearance Problems . . . . .	125
7.3.2.1	Lines . . . . .	125
7.3.2.2	Die Drool . . . . .	126
7.3.2.3	Discoloration and Degradation . . . . .	126
7.3.2.4	Voids . . . . .	128
7.3.2.5	Vent Flow . . . . .	128

---

7.3.2.6	Air Entrapment . . . . .	129
7.3.2.7	Gels . . . . .	129
7.3.2.8	Poor Mixing . . . . .	130
7.3.3	Functional Product Problems. . . . .	132
7.3.4	High Melt Temperature . . . . .	132
7.3.5	High Motor Load . . . . .	133
7.3.6	Wear Problems. . . . .	134
7.4	Systematic Problem Solving. . . . .	135
7.5	Machine Troubleshooting and Maintenance. . . . .	137
7.5.1	Check the Oil. . . . .	137
7.5.2	Unusual Noises . . . . .	138
7.5.3	Drive Motors and Belts. . . . .	139
7.5.4	Spare Parts . . . . .	140
7.5.5	Screw and Barrel. . . . .	140
7.5.6	Extruder Maintenance Checklist . . . . .	141
7.6	Troubleshooting Lists . . . . .	145
8	New Developments in Extrusion and Methods to Increase Efficiency . . . . .	151
8.1	General Trends . . . . .	151
8.2	High-Speed Extrusion . . . . .	151
8.2.1	Melt Temperature. . . . .	151
8.2.2	Extruders without Gear Reducer . . . . .	152
8.2.3	Energy Consumption. . . . .	153
8.2.4	Change-over Resin Consumption . . . . .	153
8.2.5	Change-over Time and Residence Time. . . . .	154
8.3	Multi-Strand Extrusion . . . . .	154
8.4	Reducing Material Cost . . . . .	156
8.4.1	Low Cost Filler. . . . .	156
8.4.2	Recycled Plastics. . . . .	158
8.4.3	Foamed Plastics . . . . .	158
8.4.4	Pre-compounded Material vs. In-house Compounding . . . . .	159
8.4.5	Start-up, Change-over, and Shut-down. . . . .	159
8.4.6	Polymer Processing Aids (PPA). . . . .	159
8.5	Increased Automation . . . . .	162
8.6	Efficient Extrusion . . . . .	162
8.6.1	Instrumentation . . . . .	163
8.6.2	Data Acquisition. . . . .	164
8.6.3	Feed Stock Variability. . . . .	164
8.6.4	Flood Feeding versus Starve Feeding. . . . .	165
8.6.5	Purging . . . . .	166
8.6.5.1	Melt Displacement Behavior . . . . .	166
8.6.5.2	Effect of Viscosity Differences . . . . .	169
8.6.5.3	Effect of Color . . . . .	170
8.6.5.4	Dynamic versus Static Purging Methods . . . . .	172

8.6.5.5 Purgung Agents . . . . .	174
8.6.5.6 Practical Rules to Reduce Purge Times . . . . .	175
8.6.6 Methods to Reduce Energy Consumption . . . . .	176
8.6.6.1 Energy Requirement . . . . .	176
8.6.6.2 Energy Cost per Kilogram . . . . .	177
8.6.6.3 Energy Cost per Year . . . . .	177
8.6.6.4 Barrel Cooling . . . . .	177
8.6.6.5 Heat Loss at the Extrusion Die . . . . .	178
8.6.6.6 Melt Temperature . . . . .	178
8.6.6.7 Pre-Drying . . . . .	178
8.6.6.8 Use of Filled Plastics . . . . .	179
8.6.6.9 Tips to Reduce Energy Use in Extrusion . . . . .	179
8.6.7 Flexible Manufacturing . . . . .	180
8.7 Statistical Process Control (SPC) and Design of Experiments (DOE) . . . . .	183
8.8 Causes of Process Variation . . . . .	184
8.8.1 Melt Temperature Variation . . . . .	185
8.8.2 Melting Related Instabilities . . . . .	186
8.9 Grooved Feed Extrusion . . . . .	186
8.9.1 Adjustable Grooved Feed Extruder . . . . .	187
8.10 The Rotary Channel Pump (RCP) . . . . .	188
8.11 New Developments in Mixing and Screw Design . . . . .	188
8.11.1 Elongational Mixing Devices . . . . .	188
8.11.2 Barrier Screws with Elongational Mixing Action . . . . .	189
8.11.3 Floating Sleeve Intermeshing Pin Mixer . . . . .	190
8.11.4 High Heat Transfer (HHT) Screw Design Technology . . . . .	191
8.11.5 The Single Screw Compounding Extruder (SSCE) . . . . .	192
8.12 Fiber Reinforced Plastics . . . . .	193
8.12.1 Conventional Methods to Make Fiber Reinforced Plastics . . . . .	193
8.12.2 Nexus Technology . . . . .	194
8.13 Conclusions . . . . .	195
Appendix 1 . . . . .	199
Appendix 2 Extrusion Theory . . . . .	201
Index . . . . .	209